TOWN OF SEABROOK SEWER DEPARTMENT



274 RTE 286 • PO BOX 456 WRIGHT'S ISLAND SEABROOK, NEW HAMPSHIRE 03874

REPORT OF THE SEWER DEPARTMENT

January 28, 2020

To: Board of Selectmen; William Manzi – Town Manager

From: Curtis Slayton – Acting Sewer Superintendent

This report contains contributions from each division within the sewer department as follows: Superintendent/Operations, Collections, Industrial Pre-treatment and Administration.

Each section describes activities that were completed, are ongoing or in the planning phase since the last status report.

SUPERINTENDENT / OPERATIONS

- Monthly DMR compliance reports submitted for Dec & Jan NHDES and EPA
- Planning for the Blackwater Bridge Outfall Pipe replacement is ongoing
- Review of the plant evaluation and upgrade recommendations from Weston & Sampson
- Met with Jones & Beach in regards to Hampton Falls connection to the sewer system.

Staffing:

Branden Moore, Sylas Slayton, and Joe Walker all obtained their Grade I WW Operators license while Daumanic Fucile obtained his Grade II WW Operators License. All of the above listed tested for and received their Collections System certification.

COLLECTIONS

COLLECTION SYSTEM ACTIVITIES

*See attached report submitted by Mechanic I Daumanic Fucile

INDUSTRIAL PRE-TREATMENT

- **Business verifications**: Verified 3 business locations and updated files with corrections/additional information.
- *Food Service Establishments:* Inspected grease interceptors at 7 food service establishments resulting in zero (0) Notice of Violations.
- *Inspections:* Conducted 9 inspections to ensure dischargers adhered to permit requirements.
- *Renewal Notices:* Issued 3 renewal notices to an existing business.
- Business License Applications: Approved 300 submitted license applications
- *Other:* Attended Tech Review Committee meeting on 01/14/2020 *Information submitted by IPP Manager Mario Leclerc*

$\begin{array}{c} \text{Town of Seabrook} \\ \textbf{SEWER DEPARTMENT} \end{array}$



274 RTE 286 • PO BOX 456 WRIGHT'S ISLAND SEABROOK, NEW HAMPSHIRE 03874

ADMINISTRATION

- Processed 3 sewer service applications with the new fee structure
- Processed year end data and filing
- Continued data collection for Phase 2 of the town's Asset Management Program.
- Continued updates to the towns GIS program and mapping

Information submitted by Secretary Jamie McDonald

Seabrook Wastewater Department Maintenance Report



October 4th 2019 – January 24th 2020 Mr. Slayton,

I am pleased to present the following monthly report on maintenance activities from October 4th 2019 to January 24th 2020

Despite a large amount of time spent repairing the Mill Lane pump station, there were many other major projects that were completed including several major pump replacements.

Totals and major repair items for your review are as follows:

- 245 preventative work orders were completed representing 175 hours of labor and a total cost of \$4,700
- 32 corrective work orders were completed representing 293 hours of labor and a total cost of \$82,000
- Mill Lane pump #1 was replaced and most of the suction piping, total hours spent on project are estimated but total cost believed to be \$12,000
- Both pumps were replaced at the school station totaling \$12,800
- A pump was replaced at the Pineo Farm pump station along with both MiniCas relays totaling \$11,500
- The Muffin Monster at Rocks Rd pump station was replaced for \$16,300
- Belt press feed pump #2 was rebuilt with new pistons & packing for \$4,800
- The influent composite sampler was replaced totaling \$6,100

Work Order details are on the following pages.

If you have any questions or concerns, please do not hesitate to ask.

Daumanic Fucile
Mechanic

Work Order History by Date with WO Notes 10/04/2019 To 01/31/2020

Date Complete	WO#	Equipment	Task Description	Type*	Assigned to	Hours	Labor Cost	Inventory Cost	Misc. Cost	Total Cost	Lag Time**
10/8/2019	12241	PS13 River Street Drain - River Street Drain	Corrective	С	Garret Murphy	3.00	\$88.94	\$0.00	\$9,571.72	\$9,660.66	0
			pump #1 with a brand of parts: \$9,571.72	new pumį	o				V = 2		
10/10/2019	12239	PS7-Pump #1 - Mill Lane Pump Station Pump #1	Corrective	С	Daumanic Fucile	6.00	\$145.92	\$0.00	\$640.00	\$785.92	0
			spool piece on pump # t roughly: \$640.00	1 in hope	s it would fix the su	ction leak.					
10/10/2019	12371	10-Composite Sampler - Hach Sigma 900 Max Refrigerated Sampler	Corrective	Ċ	Daumanic Fucile	1.00	\$23.93	\$0.00	\$6,098.40	\$6,122.33	0
			composite sampler witl : \$6,98.40	h a brand	new all weather un	it from Hacl	h.				
10/11/2019	12238	PS7-Check Valves - Mill Lane Pump Station Check Valves	Corrective	С	Ray Follansbee	9.00	\$230.10	\$0.00	\$83.22	\$313.32	0
		Notes: Replaced Parts cost	check flap for pump #1 : \$83.22							,	
10/11/2019	12240	MPS8-Pump #1 - Pineo Farms Pump Station Pump #1	Corrective	С	Garret Murphy	6.00	\$171.50	\$0.00	\$11,365.09	\$11,536.59	0
		relays. Total cost	pump #1 with a brand r of parts: \$10,940.09 ectrician: \$425.00	new pump	, also replaced bot	h MiniCas r	elays and hii	red Rich to co	me out and w	ire in the new p	ump and
10/17/2019	12258	PS18-Generator - Route 286 Pump	Corrective	С	Ray Follansbee	3.00	\$88.94	\$0.00	\$115.99	\$204.93	0

^{*} WO Types C-Corrective P-Preventative S-Skipped

^{**} Lag Time is defined as the Date Complete - the Date Due

Complete	WO#	Equipment	Task Description	Type*	Assigned to	Hours	Cost	Cost	Cost	Total Cost	Lag Time**
		Station Generator			·		14 11 251				
		Water pu	d water pump and 5 gall ump: \$55.99 :e: \$60.00	ons of an	tifreeze.					\$	
10/18/2019	12259	PS10-Pump #2 Motor - Ledge Road Pump Station Pump #2 Motor	Corrective	С	Ray Follansbee	2.00	\$51.99	\$0.00	\$645.00	\$696.99	
		Notes: Motor ha	id gone bad. Replaced it st: \$645.00	with a sp	pare.					· · · · ·	419 h
10/22/2019	12309	PS4-Pump #2 - Walton School Pump Station Pump #2	Corrective	С	Garret Murphy	4.00	\$118.58	\$0.00	\$6,316.33	\$6,434.91	U _ 0
			brand new replacement d Start Kit: \$6,316.33	pump fro	m Flygt Model NP-	3085.070-19	60026				
10/22/2019	12303	PS17-Muffin Monster - Rocks Road Muffin Monster	Corrective	С	Garret Murphy	2.00	\$59.29	\$0.00	\$16,245.86	\$16,305.15	C
		Notes: Replaced Price: \$1	d Muffin Monster with a b 6,245.86	orand nev	v one, reused old m	notor.					
10/29/2019	12364	70-#93 F250 Mechanic Truck - #93 2012 Ford F-250 Mechanic Truck	Corrective	С	Daumanic Fucile	1.00	\$26.23	\$0.00	\$740.00	\$766.23	0
		Notes: 4 Brand r Total: \$7									
0/30/2019	12306	Simplex 068 - 9 Virginia Lane (LaBarre, Leon)	Corrective	С	Daumanic Fucile	3.00	\$73.95	\$0.00	\$318.73	\$392.68	0
		4" cover a Bolts: \$6. Sealant: 3									

^{**} Lag Time is defined as the Date Complete - the Date Due

Date Complete	WO#	Equipment	Task Description	Type*	Assigned to	Hours	Labor Cost	Inventory Cost	Misc. Cost	Total Cost	Lag Time**
10/30/2019	12307	90-Manhole Cover - Manhole Cover and Ring	Corrective	С	Daumanic Fucile	2.00	\$49,30	\$0.00	\$313.30	\$362.60	0
	w "	Notes: Manhole Frame an Mortar: \$ Total: \$3		s broken	Replaced with a n	ew frame a	and cover.				
11/6/2019	12362	PS4-Pump #1 - Walton Road Pump Station Pump #1	Corrective	С	Ray Follansbee	4.00	\$105.94	\$0.00	\$6,316.33	\$6,422.27	0
		Notes: Installed I	orand new replacement d Start Kit: \$6,316.33	pump fro	m Flygt, Model NP-	3085.070-	1960027				
11/11/2019	12365	70-#93 F250 Mechanic Truck - #93 2012 Ford F-250 Mechanic Truck	Corrective	С	Daumanic Fucile	1.00	\$26.00	\$0.00	\$1,371,14	\$1,397.14	0
		transmiss performed	s brought to Wall's Ford ion and radiator were b 1. of repairs: \$1,371.14								
11/11/2019	12366	20-Plant Water System - Plant Water System	Corrective	С	Ray Foliansbee	5.00	\$148.23	\$0.00	\$0.00	\$148.23	0
		Notes: The blade	ers in the plant water s	ystem pre	ssure tanks had to	be refilled	with air to ma	aintain appropr	iate water pre	essure.	
11/15/2019	12368	70-#92 F350 Crane Truck - #92 2008 Ford F-350 Crane Truck	Corrective	С	Daumanic Fucile	1.00	\$23.93	\$0.00	\$137.54	\$161.47	0
			both leaking heater cor s cost: \$137.54	e hoses a	and 2 gallons of anti	ifreeze.					
11/17/2019	12367	MPS3-Wetwell - Autumn Way Pump Station Wetwell	Corrective	С	Daumanic Fucile	4.50	\$107.69	\$0.00	\$56.00	\$163.69	0
		Notes: Police call Replaced	ed reporting the alarm v	was going ood pump	off on the Autumn in lead for the nigh	Way pump it. Both pur	station. mps were pul	led and cleane	ed the next da	ay.	

^{*} WO Types C-Corrective P-Preventative S-Skipped

^{**} Lag Time is defined as the Date Complete - the Date Due

WO#	Equipment	Task Description	Type*	Assigned to	Hours	Labor Cost	Inventory Cost	Misc. Cost	Total Cost	Lag Time**
	Float cost	\$56.00								
12363	PS18-Blower #2 - Route 286 Pump Station West Side Blower	Corrective	C.	Daumanic Fucile	2.00	\$53.58	\$0.00	\$0.00	\$53.58	
	Notes: Replaced	dry-side ventilation blo	wer and r	notor with spare fro	m generat	or room.				
12436	PS17-Meter Vault - Rocks Road flowmeter & vault	Corrective	C	Daumanic Fucile	4.50	\$107.69	\$0.00	\$56.00	\$163.69	-2
	Notes: High level	alarm, replaced "on" fl	oat for su	mp pump for \$56						
12437	PS5-Pump #2 Motor - Causeway Street Pump Station Pump #2 Motor	Corrective	С	Daumanic Fucile	2.00	\$37.93	\$0,00	\$600.00	\$637.93	0
	Notes: Replaced	motor, new motor cost	\$600							
12471	Simplex 010 - 58 Blacksnake Road (Catalano, Robert & Wanda)	Corrective	С	Garret Murphy	3.00	\$88.94	\$0.00	\$915.62	\$1,004.56	0
	Notes: Pump was	burned out and was re	eplaced w	ith a brand new one	ofor \$915.	62				
12472	Simplex 014 - 45B Collins Street (Frascone, Mary Anne)	Corrective	С	Garret Murphy	2.00	\$59.29	\$0.00	\$58.90	\$118.19	, , , ° 0
12473	Simplex 027 - 26 Cross Beach (Felch, Lorenda)	Corrective	С	Garret Murphy	2.00	\$59.29	\$0.00	\$58.90	\$118.19	0
12469	PS7-Pump #1 - Mill	Corrective	С	Garret Murphy	180.00	\$4,614.40	\$0.00	\$6,537.00	\$11,151.40	1
	12436 12436 12437 12471	Float cost 12363 PS18-Blower #2 - Route 286 Pump Station West Side Blower Notes: Replaced 12436 PS17-Meter Vault - Rocks Road flowmeter & vault Notes: High level 12437 PS5-Pump #2 Motor - Causeway Street Pump Station Pump #2 Motor Notes: Replaced 12471 Simplex 010 - 58 Blacksnake Road (Catalano, Robert & Wanda) Notes: Pump was 12472 Simplex 014 - 45B Collins Street (Frascone, Mary Anne) Notes: Replaced Cost: \$58. 12473 Simplex 027 - 26 Cross Beach (Felch, Lorenda) Notes: Replaced Cost: \$58.	Float cost: \$56.00 12363 PS18-Blower #2 - Corrective Route 286 Pump Station West Side Blower Notes: Replaced dry-side ventilation blowner Notes: Replaced dry-side ventilation blowner Rocks Road flowmeter & vault Notes: High level alarm, replaced "on" flowner Pump #2 Motor - Causeway Street Pump Station Pump #2 Motor Notes: Replaced motor, new motor cost Replaced motor, new motor cost Replaced Road (Catalano, Robert & Wanda) Notes: Pump was burned out and was refered to the Road Road (Catalano, Robert & Wanda) Notes: Pump was burned out and was refered to the Replaced Burned out contacter Cost: \$58.90 12473 Simplex 027 - 26 Corrective Cross Beach (Felch, Lorenda) Notes: Replaced burned out contacter Cost: \$58.90 Notes: Replaced burned out contacter Cost: \$58.90	Float cost: \$56.00 12363 PS18-Blower #2 - Corrective C Route 286 Pump Station West Side Blower Notes: Replaced dry-side ventilation blower and r Notes: Replaced dry-side ventilation blower and r Rocks Road flowmeter & vault Notes: High level alarm, replaced "on" float for sure 12437 PS5-Pump #2 Corrective C Motor - Causeway Street Pump Station Pump #2 Motor Notes: Replaced motor, new motor cost \$600 12471 Simplex 010 - 58 Corrective C Blacksnake Road (Catalano, Robert & Wanda) Notes: Pump was burned out and was replaced w Wanda) Notes: Pump was burned out and was replaced w (Frascone, Mary Anne) Notes: Replaced burned out contacter Cost: \$58.90 12473 Simplex 027 - 26 Corrective C Cross Beach (Felch, Lorenda) Notes: Replaced burned out contacter Cost: \$58.90	Float cost: \$56.00 12363 PS18-Blower #2 - Corrective C Daumanic Fucile Route 286 Pump Station West Side Blower Notes: Replaced dry-side ventilation blower and motor with spare fro 12436 PS17-Meter Vault - Corrective C Daumanic Fucile Rocks Road flowmeter & vault Notes: High level alarm, replaced "on" float for sump pump for \$56 12437 PS5-Pump #2 Corrective C Daumanic Fucile Motor - Causeway Street Pump Station Pump #2 Motor Notes: Replaced motor, new motor cost \$600 12471 Simplex 010 - 58 Corrective C Garret Murphy Blacksnake Road (Catalano, Robert & Wanda) Notes: Pump was burned out and was replaced with a brand new one Collins Street (Frascone, Mary Anne) Notes: Replaced burned out contacter Cost: \$58.90 12473 Simplex 027 - 26 Corrective C Garret Murphy Cross Beach (Felch, Lorenda) Notes: Replaced burned out contacter Cost: \$58.90	Float cost: \$56.00 12363 PS18-Blower #2 - Corrective C Daumanic Fucile 2.00 Route 286 Pump Station West Side Blower Notes: Replaced dry-side ventilation blower and motor with spare from generate Rocks Road flowmeter & vault Notes: High level alarm, replaced "on" float for sump pump for \$56 12437 PS5-Pump #2 Corrective C Daumanic Fucile 2.00 Motor - Causeway Street Pump Station Pump #2 Motor Notes: Replaced motor, new motor cost \$600 12471 Simplex 010 - 58 Corrective C Garret Murphy 3.00 Blacksnake Road (Catalano, Robert & Wanda) Notes: Pump was burned out and was replaced with a brand new one for \$915. 12472 Simplex 014 - 45B Corrective C Garret Murphy 2.00 Collins Street (Frascone; Mary Anne) Notes: Replaced burned out contacter Cost: \$58.90 12473 Simplex 027 - 26 Corrective C Garret Murphy 2.00 Cross Beach (Felch, Lorenda) Notes: Replaced burned out contacter Cost: \$58.90	Float cost Flo	Float cost: \$56.00 Float cost: \$56.00 PS18-Blower #2 - Corrective C Daumanic Fucile 2.00 \$53.58 \$0.00 Route 286 Pump Station West Side Blower Rotes: Replaced dry-side ventilation blower and motor with spare from generator room. 12436 PS17-Meter Vault - Corrective C Daumanic Fucile 4.50 \$107.69 \$0.00 Rocks Road flowmeter & vault Notes: High level alarm, replaced "on" float for sump pump for \$56 12437 PS5-Pump #2 Corrective C Daumanic Fucile 2.00 \$37.93 \$0.00 Rocks Road flowmeter & vault Notes: Replaced motor, new motor cost \$600 12447 PS5-Pump #2 Corrective C Daumanic Fucile 2.00 \$37.93 \$0.00 Rocks Road (Catalano, Robert & Road (Catalano, Robert & Wanda) Robert & Wanda) Robert & Wanda) Rotes: Pump was burned out and was replaced with a brand new one for \$915.62 12472 Simplex 014 - 45B Corrective C Garret Murphy 2.00 \$59.29 \$0.00 Collins Street (Frascone; Mary Anne) Notes: Replaced burned out contacter Cost: \$58.90 12473 Simplex 027 - 26 Corrective C Garret Murphy 2.00 \$59.29 \$0.00 Rotes: Replaced burned out contacter Cross: \$58.90 12473 Simplex 027 - 26 Corrective C Garret Murphy 2.00 \$59.29 \$0.00 Rotes: Replaced burned out contacter Cross: \$58.90 12473 Rotes: Replaced burned out contacter Cost: \$58.90 12473 Rotes: Replaced burned out contacter Cost: \$58.90	Task Description Type* Assigned to Hours Cost Cost Cost	Float cost

^{**} Lag Time is defined as the Date Complete - the Date Due

Date Complete	WO#	Equipment	Task Description	Type*	Assigned to	Hours	Labor I	nventory Cost	Misc. Cost	Total Cost	Lag Time**
		Pump #1	W 				777 - 24-			10	
		Cost of p	l pump with brand new ump: \$6,337.00 ts: \$200.00	4" Super	T from Gorman Ru	рр	140 to 14				
12/26/2019	12508	PS7-Misc - Mill Lane Pump Station Miscellaneous	Corrective	С	Garret Murphy	5.00	\$137.90	\$0.00	\$200.00	\$337.90	C
	i puñ	tightened	routing new drain hose bolts at all suction join gh cost of materials: \$2	ts, and fille				dump into v	vet well, re-cal	ked several join	ts,
/2/2020	12507.	PS10-Pump #1 - Ledge Road Pump Station Pump #1	Corrective	C	Daumanic Fucile	5.00	\$123.26	\$0.00	\$150.00	\$273.26	O
			l pump and replaced fa t roughly \$150.00	ulty air rei	ease valve with a r	ebuilt spare.	. Also rerouted	air release	drain with flex	ible hose.	
/3/2020	12511	PS19-Odor Control Blower - Centennial Street Pump Station Odor Control Blower	Corrective	С	Daumanic Fucile	2.00	\$51.99	\$0.00	\$140.18	\$192.17	0
			sump pump in biofilter o: \$140.18				*				
/9/20 <u>2</u> 0	12512	80-Treatment Plant Grounds - Groundscape	Corrective	С	Daumanic Fucile	1.50	\$35.90	\$0.00	\$94.00	\$129.90	1
		Notes: Replaced Parts: \$94	thermostat and heater	fan relay	in garage.						
/9/2020	12553	60-BFP Feed Pump#2 - Belt Filter Press Feed Pump #2	Corrective	С	Ray Follansbee	15.00	\$384.50	\$0.00	\$4,383.78	\$4,768.28	. 0
					packing. Oil and Misc: \$30	ı					
/10/2020	12513	PS16-General - Route 107 Pump	Corrective	С	Garret Murphy	1.00	\$29.65	\$0.00	\$15.00	\$44.65	0

^{*} WO Types C-Corrective P-Preventative S-Skipped

^{**} Lag Time is defined as the Date Complete - the Date Due

Date Complete	WO#	Equipm	ent	Task Description	Type* Assigned to) Hours	Labor Cost	Inventory Cost	Misc. Cost	Total Cost	Lag Time**
		Station Bi Grnds Notes:		furnace overtemp senso	r with one that autores	ets upon cooldo	own.	- 1 s			
1/15/2020	12529	60-BFP#1 Filter Pres		Corrective	C Daumanic Fu	cile 7.50	\$200.27	\$0.00	\$722.00	\$922.27	. 0
1/17/2020	12531	90 All Pur Stations - stations, o	New belt: np All pump		nd new one from NFM C Ray Follansbe	ee 3.00	\$88.94	\$0.00	\$92.00	\$180.94	2
		Notes:		air filters replaced with to scost: \$92.00	Napa Gold Filter #2095	å					
Summary Total # o Total Ho Average		*	32 293.00 0.25	Total Labor Cos Total Inventory (Total Misc Cost Total Cost	Cost \$0.	00 03					

^{*} WO Types C-Corrective P-Preventative S-Skipped

^{**} Lag Time is defined as the Date Complete - the Date Due